

: K T - R F T F



K I N T E K

1 1 0 0 ° C

	×			
K T - R F T F 2 0 2 0	2 0 0 × 2 0 0 0 mm	9 5 0	3	3 0
K T - R F T F 3 0 3 0	3 0 0 × 3 0 0 0 mm	9 5 0	6	5 4
K T - R F T F 4 0 5 0	4 0 0 × 5 0 0 0 mm	9 5 0	6	9 6
K T - R F T F 5 0 6 0	5 0 0 × 6 0 0 0 mm	9 5 0	6	1 6 8
K T - R F T F 6 0 8 0	6 0 0 × 8 0 0 0 mm	9 5 0	9	2 3 4
K T - R F T F 8 0 9 0	8 0 0 × 9 0 0 0 mm	9 5 0	9	3 4 2
K T - R F T F 1 2 1 1	1 2 0 0 × 1 1 0 0 0 mm	9 5 0	9	6 4 8