

K f I s o

: K T - V A 1 2



K F / I S O

3 0 4 / 3 1 6 S S

/ E

K F I S O

	A	B	C	D
I S O 6 3	9 5	1 2	7 0	9 0
I S O 8 0	1 1 0	1 2	8 3	1 0 5
I S O 1 0 0	1 3 0 mm	1 2	1 0 2	1 2 5
I S O 1 2 5	1 5 5	1 2	1 2 7	1 5 0
I S O 1 6 0	1 8 0	1 2	1 5 3	1 7 5
I S O 2 0 0	2 4 0 mm	1 2	2 1 3	2 3 5
I S O 2 5 0	2 9 0	1 2	2 6 1	2 8 5
I S O 3 2 0	3 7 0	1 7	3 1 8	3 6 5
I S O 4 0 0	4 5 0	1 7	4 0 0	4 4 5
I S O 5 0 0	5 5 0 mm	1 7 mm	5 0 1	5 4 5
I S O 6 3 0	6 9 0	2 2	6 5 1	6 8 5

	A	B
K F 1 0	1 2 . 2	3 0
K F 1 6	1 7 . 2	3 0
K F 2 5	2 6 . 2	4 0
K F 4 0	4 1 . 2	5 5
K F 5 0	5 2 . 2	7 5
K F 6 3	7 0	8 7
K F 8 0	8 3	1 1 4
K F 1 0 0	1 0 2	1 3 4
K F 1 6 0	1 5 3	1 9 0

	A	B	C *	P . C . D
--	---	---	-----	-----------

CF16	34	7.5	4.4*6	26.9
CF25	54	10.5	6.6*6	43
CF35	70	12.7	6.7*6	58.7
CF50	86	16	8.4*8	72.4
CF63	114	18	8.4*8	92.1
CF80	130	18	8.4*16	110
CF100	152	20	8.4*16	130.3
CF150	202	22	8.4*20	181
CF200	253	24.5	8.4*24	231.8
CF250	305	26	8.4*32	284
CF300	368	28.5	10.8*36	338.1
CF350	419.1	28.5	10.8*36	388.9