

S i c

: K T - S H



1 6 0 0 ° C

6 0 0 -

	H Z	C Z	O L	
8	1 0 0 - 3 0 0	6 0 - 2 0 0	2 4 0 - 7 0 0	2 . 1 - 8 . 6
1 2	1 0 0 - 4 0 0	1 0 0 - 3 5 0	3 0 0 - 1 1 0 0	0 . 8 - 5 . 8
1 4	1 0 0 - 5 0 0	1 5 0 - 3 5 0	4 0 0 - 1 2 0 0	0 . 7 - 5 . 6
1 6	2 0 0 - 6 0 0	2 0 0 - 3 5 0	6 0 0 - 1 3 0 0	0 . 7 - 4 . 4
1 8	2 0 0 - 8 0 0	2 0 0 - 4 0 0	6 0 0 - 1 6 0 0	0 . 7 - 5 . 8
2 0	2 0 0 - 8 0 0	2 5 0 - 6 0 0	7 0 0 - 2 0 0 0	0 . 6 - 6 . 0
2 5	2 0 0 - 1 2 0 0	2 5 0 - 7 0 0	7 0 0 - 2 6 0 0	0 . 4 - 5 . 0
3 0	3 0 0 - 2 0 0 0	2 5 0 - 8 0 0	8 0 0 - 3 6 0 0	0 . 4 - 4 . 0
3 5	4 0 0 - 2 0 0 0	2 5 0 - 8 0 0	9 0 0 - 3 6 0 0	0 . 5 - 3 . 6
4 0	5 0 0 - 2 7 0 0	2 5 0 - 8 0 0	1 0 0 0 - 4 3 0 0	0 . 5 - 3 . 4
4 5	5 0 0 - 3 0 0 0	2 5 0 - 7 5 0	1 0 0 0 - 4 5 0 0	0 . 3 - 3 . 0
5 0	6 0 0 - 2 5 0 0	3 0 0 - 7 5 0	1 2 0 0 - 4 0 0 0	0 . 3 - 2 . 5
5 4	6 0 0 - 2 5 0 0	3 0 0 - 7 5 0	1 2 0 0 - 4 0 0 0	0 . 3 - 3 . 0

	2 . 5 /
--	---------

2 3 %

	1 4 - 1 9 W / m - K 1 0 0 0 ° C
--	---------------------------------

5 0 M P a 2 5 ° C

	1 . 0 k J / k g - K 2 5 ~ 1 3 0 0 ° C
--	---------------------------------------

4 . 5 × 1 0 - / K